

# General Environmental Incident Summary

**Incident:** 3320      **Date/Time Notice:** 5/14/2014      18:28      **DEM Incident No:**  
**Responsible Party:** Crestwood Crude Logistics LLC  
**Date Incident:** 5/14/2014      **Time Incident:** 16:40      **Duration:** 1 minutes  
**County:** Williams      **Twp:** 156      **Rng:** 99      **Sec:** 1      **Qtr:**  
**Lat:** 48.28211      **Long:** -103.35290      **Method:** Interpolation from map  
**Location Description:** Colt Terminal  
12324 60th Street  
Epping, ND 58843  
**Submitted By:** Don Butler      **Affiliation:**  
**Address:** 801 Cherry Street  
**City:** Fort Worth      **State:** TX      **Zip:**

## Received By:

**Contact Person:** Don Butler  
801 Cherry Street  
Suite 3800/Unit 20  
Fort Worth, TX 76102

**Distance Nearest Occupied Building:** 600 Feet      **Release Contained:** Yes  
**Type of Incident:** Localized Release at Pipeline Pig Receiving Station  
**Description of Released Contaminant:** Crude oil  
**Volume Spilled:**      **Ag Related:** No  
**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** No

## Cause of Incident:

Wholly inside facility confines, at conclusion of pipeline pigging operations, a small localized release of crude oil resulted during pig removal, impacting approx. 10-ft by 10-ft surface area.

## Risk Evaluation:

None

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

Localized impact to soil only, measuring approx. 10-ft x 10-ft surface area.

No water impacted.

## Action Taken or Planned:

Source immediately stopped, impacted soil removed and being properly stored onsite for transportation to third-party remedial services.

**Wastes Disposal Location:** A third-party soil remediation service.

## Agencies Involved:

## **Updates**

---

**Date:** 5/14/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Volume:**

**Notes:**

Release of oil at a pipeline pigging station. Followup is necessary.

---

**Date:** 5/23/2014    **Status:** Inspection

**Author:** Martin, Russell

**Updated Volume:**                      15.00 gallons

**Notes:**

5/23/2014 at 11:15, on location. Met with site personnel and visited site of incident. According to personnel, beneath the pig launcher is a pipe that takes any oil coming out of the pig launcher line to a waste oil tank to the southwest. The incident occurred when this pipe clogged, so the next time oil went through it to the waste oil tank, it instead went out a vent in the pipe. Facility dirt has been scraped up into a pile, with a tarp placed over it. Concrete around the pipe vent is still stained. Absorbent boom has been placed around the spill in case it rains. The soil remediation for the incident is still being bid. Report contact will notify once a company has been chosen and material has been removed. Recommended to personnel that a tarp should be placed underneath the impacted material as well, so that any liquids within the impacted material do not also impact the facility ground upon which it is placed.

---

**Date:** 5/28/2014    **Status:** Correspondence

**Author:** Martin, Russell

**Updated Volume:**

**Notes:**

Email from facility personnel with disposal location as Prairie Disposal.

---

**Date:** 6/8/2014    **Status:** Correspondence

**Author:** Martin, Russell

**Updated Volume:**

**Notes:**

Email from report contact; cleanup is complete.

**Updated Volume:**

**Notes:**

9/16/2014 at 11:40, on location. Met with facility personnel and supervisor in charge of cleanup. Visited site of incident. Area around the incident site is being excavated to reroute lines at the facility, but the exact location of the incident has not been excavated yet. No visible staining to ground and no visibly stained soil in the piles being excavated.